### Valley Stream Thirteen Union Free School District

Phase 1 – Roof Replacement / Chimney Reconstruction November 2016 Progress Report



PARK EAST CONSTRUCTION CORP.



## VALLEY STREAM 13 SCHOOL DISTRICT



### Willow Elementary Roof Replacement : <u>BBR CONTRACTING</u>


- Removal of existing roofing system / abatement complete
- New roofing system / including new wood blocking complete
- Window repair due to dumpster damage complete- new unit ventilator installed/ complete
- Exterior edge / fascia installation complete
- Punch List complete
- Close out In Progress

#### Chimney Reconstruction : PELLA CONSTRUCTION

- Demolition of existing chimney (top 8' feet) complete
- Installation of new fire brick and face brick complete
- Installation of new stainless steel chimney cap complete
- Replacement of existing concrete entry pad complete
- Punch List complete
- Close out- In Progress



### **Willow Elementary**





### **Howell Elementary**

#### Roof Replacement : BBR CONTRACTING


- Removal of existing roofing system / abatement complete
- New roofing system/ including new wood blocking complete
- Installation of new thru wall flashing at gym complete
- Exterior perimeter fascia blocking complete
- Punch list complete
- Close Out- In Progress

#### Chimney Reconstruction : PELLA CONTRACTING

- Demolition of existing chimney (top 6' feet) complete
- Installation of new fire brick and face brick complete
- Installation of new stainless steel chimney cap complete
- Replacement of existing concrete entry pad complete
- Punch list complete
- Close Out- In Progress



### **Howell Elementary**





### **Dever Elementary**

#### Roof Replacement: BBR CONTRACTING


- Canopy demo/ abatement complete
- New roofing system / including new wood blocking complete
- Exterior perimeter fascia complete
- Punch list complete
- Close out- In Progress

#### Chimney Reconstruction: Pella Construction

- Demolition of existing chimney (top 18' feet) complete
- Installation of new fire brick and face brick complete
- Installation of new stainless steel chimney cap complete
- All concrete entry pads have been replaced, work completed
- Punch list complete
- Close out- In Progress



### **Dever Elementary**





### **Wheeler Elementary**

#### Roof Replacement : BBR CONTRACTING


- Removal of existing roofing system / abatement complete
- New roofing system / including new wood blocking complete
- Window repair due to dumpster damage complete- new unit ventilator installed/ complete
- Exterior edge / fascia installation complete
- Punch List complete
- Close out In Progress

#### Chimney Reconstruction : PELLA CONTRACTING

- Demolition of existing chimney complete (top 18' feet)
- Installation of fire brick and exterior face brick complete
- Chimney cap installation complete
- Punch list complete
- Close Out- In Progress



### **Wheeler Elementary**





# PARK EAST CONSTRUCTION CORP.